



Resting on one of its base point on **HP**, axis and base inclined with HP



Resting on one of its base point on **VP**

Resting on one of its generator on **HP** and axis inclined to **VP**



FREELY SUSPENDED SOLIDS SIMPLE POSITION

Simple position for freely suspended solids, one of the corner must be in the extreme left hand side.

