



* With the help of combination of set square we are able to draw lines at 15° increment.




→ Set Squares

3) Engineering Compass → Used to draw arc, circle and sometimes to join the curves.

Two types :-

(i) Large Compass - Radius greater than 20 mm

(ii) Small Bow Compass - Radius < 50 mm



Bow Compass



→ Needle Box of Pencil

4) Divider → Used to divide line arc, circle in equal and proportional part with accuracy